



Tangla Fire & Emergency Services Station
Dist- Udalguri (Assam).



No. TNL/F&ESS/75/ 110

/26

Dated.11/05/2026

To,

The Principal,

For "RADIANCE SCHOOL DIMAKUCHI"
VIII-NO 1 UTTAR DIMAKUCHI,
UDALGURI TAMULPUR ROAD
Dist- UDALGURI (Assam).

Sub: - Implementation of Fire Prevention and Fire safety Measures in the existing School building of "RADIANCE SCHOOL DIMAKUCHI" bearing Dag No:226&Patta No:-04,Mouza-Sekhar located at Vill-No.1 Uttar Dimakuchi,UdalguriTamulpur Road ,Dist- Udalguri(Assam).

Ref:-FNESBNOCI/2026/01323

Sir,

With reference to the subject cited above, you are requested to implement of the following minimum Fire Prevention and Fire Safety Measures in the above noted Academic building for safety of lives and properties as well as the building itself.

I. Recommendation of Fire Prevention and Fire safety measures as per N.B.C, 2016 PART- 4, Fire & Life Safety


1. Open Space as shown around the school building should be kept free from any obstruction for movement of fire & emergency services vehicle in case of any emergency.
2. **Passageways and Clearances:-**
 - a) Width of the main entrance of the Building premises shall not be less than 4.5 mtr.
 - b) If an arch or covered gate is constructed, it shall have a clear head-room of not less than 5mtr.
3. A Fire Point consists of 03 (three) Nos. Fire bucket, 03 (three) Nos. of sand bucket, should be made available in-front of the school building.
4. Manually Operated Electric Fire Alarm system should be provided in the building in accordance with IS 2175:1988,11360:1985 and IS 2189:1999

5.Fire Extinguishers:-

- I. Adequate numbers of ABC or D.C.P extinguisher of 4/6Kg capacity with ISI mark should be installed in the building. The extinguishers shall be distributed over the floor area such that a person has to travel not more than 15 mtrs. to reach the nearest extinguisher or in each 100 sqmtr. in floor area.
 - II. Adequate numbers of Co₂ Extinguisher of 4.5 kg capacity With ISI mark should be installed near the main Electric Panel board /Switch gear room/DG set room.
 - III. Adequate number of CO₂ Extinguisher of capacity 4.5 kg with ISI mark should be installed at Laboratory and computer room.
 - IV. One AFFF extinguisher of 09 Ltrs.capacity with ISI mark shall be provided near the Generator and Transformer.
- II. N.B:-All extinguishers should be as per newly introduced Indian Standard -IS 15683:2006.**

6. Staircase/passages should always free from any obstruction.

7. Electric Wiring of the buildings should be either conduit or Concealed type.


Manager

SMC

Radiance School Dimakuchi

8. Lightning conductor should be provided to protect the building from lightning disaster.
9. To eliminate fire hazards, good housekeeping both outside and inside of the building shall be strictly maintained by the staff and management in the building.
10. The staffs should be trained up how to operate the Fire fighting equipment as and when required.
11. A Fire fighting plan should be prepared. It should consist of Emergency Management teams. The members should be trained to operate the Fire fighting systems.
12. Emergency Telephone Numbers should be displayed in and around the building.
13. Any alteration/modification and change of the building should be informed to the undersigned for taking necessary action.

PLEASE DO NOT TREAT THIS AS N.O.C, FORMAL N.O.C WILL BE ISSUED BY THE ADGP CUM DIRECTOR OF FIRE & EMERGENCY SERVICES, ASSAM ONLY AFTER IMPLEMENTATION OF THE FIRE PREVENTIVE MEASURES AS SUGGESTED AND ON RECEIPT OF COMPLIANCE REPORT FROM YOUR END AND AFTER SUBMISSION OF SATISFACTORY INSPECTION REPORT BY TECHNICAL OFFICERS OF THIS DEPARTMENT

Yours Faithfully


11/05/2026

Station Officer

Station Officer
Tangla Fire & Emergency Services station
Udalguri, BTAD (Assam)

Tangla Fire & Emergency Services Station
Dist- Udalguri(Assam).

Memo No. TNL/F&ESS/75/110 /26

Dated. 11/05/2026

Copy to:-

1. The ADGP cum Director of Fire & Emergency Services, Assam, Guwahati for favour of kind information and necessary action.


Station Officer


11/05/2026

Station Officer

Tangla Fire & Emergency Services station
Udalguri, BTAD (Assam)

Tangla Fire & Emergency Services Station
Dist- Udalguri (Assam).


Manager

SMC

Radiance School Dimakuchi