

SAFE DRINKING WATER AND SANITATION CONDITION



Email-tanglaphedivision@outlook.com


No. PHEE/TNL/ TB-225 / 2025-26/ 2524

Date..03/06/2025

It is certified that an inspection team of Tangla District Level Laboratory from Office of the Executive Engineer (PHE) Tangla Division, Tangla inspected the **RADIANCE SCHOOL, DIMAKUCHI** Village:-No- 01 Uttar Dimakuchi, P.O:-Dimakuchi, Udalguri, (BTR) Assam, Pin- 784526 on 31st May, 2025 and found that the **RADIANCE SCHOOL, DIMAKUCHI** has safe drinking water facilities for the students and members of staff of institution and is maintaining the hygienic sanitation condition in the School building & the campus.

This above is valid for a period of 6(six) months.

Verified By


Asstt. Chemist (PHE)
Tangla DLL
Tangla


Nodal Officer
Tangla DLL
Tangla


Manager
SMC Radiance School
Dimakuchi